## NGA LIST OF LIGHTS CORRECTIONS

**PUB 111 Ed 2009 NEW EDITION**
(NGA) 45/09

**PUB 113 Ed 2009 NEW EDITION**
(NGA) 45/09

## SAILING DIRECTIONS CORRECTIONS

**PUB 172 15 Ed 2009 NEW EDITION**
(NGA) 45/09

## COAST PILOT CORRECTIONS

**COAST PILOT 3 42 Ed 2009 Change No. 14**
**LAST NM 41/09**

Page 186—Paragraph 34, lines 3 to 5; read:

**Manasquan River**. In May 2009, the controlling depth was 11.4 feet in the inlet though the jetties, thence the controlling depth was 8.7 feet (9.3 feet at …
(BP 192941; BP 192943) 45/09

Page 187—Paragraph 53, lines 4 to 12; read:

respectively, above the inlet entrance south jetty. The New Jersey Intracoastal Waterway is described in Chapter 5. In October 2007, the controlling depth was 9.5 feet to Clam Creek; thence in February 2009, 3.0 feet in Clam Creek entrance channel with shoaling to lesser depths in the north half of the channel, with depths of 10.9 to 15.0 feet in the basin. The …
(CL 1156/09; BP 193274; 47/04 CG5; LL/09) 45/09

Page 229—Paragraph 306, lines 2 to 8; read:

lights, and the entrance channel is marked by buoys. (See Local Notice to Mariners and latest editions of charts for controlling depths.) The mean range of …
(NOS 12312) 45/09

Page 251—Paragraph 37, line 3; read:

miles above the inlet. In 1995-2009, the controlling …
(BPs 193316-17) 45/09

Page 265—Paragraph 58, lines 2 to 4; read:

Light, is subject to continual change. In June 2008, the controlling depth in the entrance channel was 7.5 feet (9.1 feet at midchannel). The inlet is marked by lights, …
(CL 1023/09; BPs 193384-87) 45/09

Page 265—Paragraph 59, lines 1 to 13; read:

Broad Bay can be reached through a dredged channel eastward from the north end of the basin, and another dredged channel eastward from the south end of the basin; the southerly channel is marked by a light and daybeacons. The north and south channels coverage near Daybeacon 10, and continue eastward to **Broad Bay**. The channel to Broad Bay is marked by daybeacons; a light is at the east end of the dredged channel, in Broad Bay. In June 2008, the controlling depth was 2.2 feet in the basin, thence 6.2 feet in the northerly channel and 4.2 feet in the southerly channel to Daybeacon 10, thence 3.4 feet in the …
(CL 1023/09; BPs 193384-91) 45/09

Page 265—Paragraph 62, lines 4 to 5; read:

**Linkhorn Bay** near Virginia Beach. In June 2008, the controlling depth was 6 feet to head of the project at …
(CL 1023/09; BPs 193392-94) 45/09

Page 300—Paragraph 158, lines 4 to 7; read:

bridge about 0.6 mile above the mouth. In December 2008, the controlling depth was 4.1 feet (6 feet at midchannel) to the mouth of the creek, thence 6.4 feet to the turning basin, thence 1.8 to 4.6 feet in the turning …
(CL 949/09; BPs 193365-68) 45/09

Page 307—Paragraph 28, line 6; read:

natural channel in the river. In January 2008, the controlling …
(CL 1347/09; DD 15652) 45/09

Page 351—Paragraph 233, lines 3 to 6; read:

to a basin about halfway up the creek. In August 2007, the midchannel controlling depth was 5.1 feet in the channel to the basin, thence 5.6 to 6 feet in the basin. The largest marine …
(CL 1346/09; DD 15651) 45/09