

## UNITED STATES COAST PILOT CORRECTIONS

**COAST PILOT 1      37 Ed 2007      Change No. 15  
LAST NM 5/08**

Page 280—Paragraph 228, lines 7 to 8; read:

above Cross River, affords anchorage in 47 to 60 feet; Merrill Ledge is northeastward of the anchorage. To reduce risk of vessel collisions and increase safety of life and property in Edgecomb, the Coast Guard establishes a **general anchorage area** just off the southwestern end of Davis Island. (See **110.1 and 110.131**, chapter 2, for limits and regulations.)

The ...

(FR 12/12/07; NOS 13293) 7/08

Page 284—Paragraph 296; strike out.

(DB 16196) 7/08

Page 306—Paragraph 665, lines 6 to 9; read:

and a 30-foot anchorage off Fish Point. In June 2006, the controlling depths were 45 feet in the entrance from the sea to Fort Gorges Island Ledge Lighted Buoy 4; thence in February-July 2005, 30.8 feet (32.5 feet at ...

(CL 1126/06; BPs 189760-61) 7/08

Page 306—Paragraph 666, line 6; read:

use the main channel. In November 2007, it was reported that an obstruction covered 5 feet was located in the channel in about 43°38.9'N., 70°11.6'W. Mariners transiting the channel are advised to use caution between Daybeacon 3 and Buoy 6.

(CL 1394/07; LL/07) 7/08