

UNITED STATES COAST PILOT CORRECTIONS

COAST PILOT 1      39 Ed 2009      Change No. 10  
LAST NM 48/09

Page 151—Paragraph 102, line 2; read:  
depth of 27 fathoms and lies about 40 miles southeast ...  
(W 00195; DD 14722)      51/09

Page 151—Paragraph 103, line 2; read:  
13 fathoms in places, is about 27 miles long. **Ammen Rock**  
...  
(W 00195; DD 14722)      51/09

Page 304—Paragraph 529, line 8; read:  
10 feet. In August 2008, a temporary bridge was under construction approximately 150 feet east of the State Route 24 highway bridge as a platform to be used for rehabilitation work on the bridge. Mariners are advised to exercise caution. An overhead power cable at the bridge has a ...  
(CL 1276/09)      51/09

Page 335—Paragraph 219, lines 8 to 10; read:  
the turning basin, thence 35 feet in the basin. The entrance and harbor ...  
(FE 00553)      51/09

Page 343—Paragraph 335, line 4; read:  
About 2.4 miles above the bridge with a reported clearance of 21 ...  
(CL 1505/09)      51/09

Page 377—Paragraph 209, line 7; read:  
and a 50-foot marine railway are available. A pumpout facility is available at Seaport Landing Marina at the head of the harbor.  
(CL 480/09)      51/09

Page 401—Paragraph 26, line 4 to Page 402—Paragraph 26, line 9; read:  
the harbor. In October 2007, the controlling depth was 8.5 feet (10.0 feet at midchannel), thence 10 feet in the basin with lesser depths along the west limit. Another dredged anchorage basin north of the entrance channel, just inside the jetties, had depths of 7.1 to 9.5 feet with shoaling along the ...  
(CL 1521/09)      51/09