

SECTION II
NAVIGATION PUBLICATIONS

NM 4/09

SAILING DIRECTIONS CORRECTIONS

PUB 142	11 Ed 2008	NEW EDITION
(NGA)		4/09

COAST PILOT CORRECTIONS

COAST PILOT 5	36 Ed 2008	Change No. 11
		LAST NM 51/08

Page 103—Paragraph 1262, line 4; read:
connects to the STL buoy.

**§150.380 Under what circumstances may vessels operate
within the safety zone or area to be avoided?**
(33 CFR 150.380) 4/09

Page 558—Paragraph 140, lines 3 to 6; read:
E from shore, has a 730-foot S face and a 930-foot N face,
and depths of 36 to 38 feet alongside. Just N is the Home
Port Dock, which is 439 feet with a depth of 23 ...
(DB 16956) 4/09

Page 567—Paragraph 282, lines 1 to 2; read:
Small ...
(CL 1250/08) 4/09