

SECTION II
NAVIGATION PUBLICATIONS

NM 32/15

SAILING DIRECTIONS CORRECTIONS

PUB 159	16 Ed 2015	NEW EDITION
(NGA)		32/15

COAST PILOT CORRECTIONS

COAST PILOT 2	44 Ed 2014	19 JUL 2015
		LAST NM 13/15

Chapter 5—Paragraph 83; read:

⁽⁸³⁾ Woods Hole Passage is a dangerous waterway surrounded by treacherous shoals, ledges and severe east/west currents. Particular attention should be given to the navigational aids that mark the passage, especially Woods Hole Passage Junction Buoy SB at the intersection of The Strait and Broadway. Before attempting to transit the passage, mariners should carefully consult the current edition of nautical charts for the area and the most recent Local Notice to Mariners. Mariners are further cautioned to always use extreme care and prudent speed when transiting the passage. Tidal currents are strong in the passage; buoys in the narrowest part of the channel are sometimes towed under by the current. Strangers to the area should attempt transit only at slack water.

(L 1137-2015; LL 2015)

32/15