

SECTION II
NAVIGATION PUBLICATIONS

NM 21/15

SAILING DIRECTIONS CORRECTIONS

PUB 171	12 Ed 2015	NEW EDITION
(NGA)		21/15

COAST PILOT CORRECTIONS

COAST PILOT 5	43 Ed 2015	NEW EDITION
(NOS)		21/15

COAST PILOT 6	45 Ed 2015	03 MAY 2015
		LAST NM 9/15

Chapter 6—Paragraph 206; read:

⁽²⁰⁶⁾ A state park and small-craft basin are on the east side of Buffalo Outer Harbor about 2.3 miles southeast of the mouth of Buffalo River. The basin has a marina with 1,000 slips and launching ramps.

(L 710-2015) 21/15

Chapter 11—Paragraph 51.01; read:

^(51.01) Several submarine cables and pipelines cross the Straits of Mackinac west of the Mackinac Bridge. These cables and pipelines rest on the lake bottom and can be easily fouled by anchors or gear. In view of the serious consequences resulting from damage to submarine cables and pipelines, vessel operators should take special care when anchoring, fishing or engaging in underwater operations near these areas. Mariners are also warned that the areas where cables and pipelines were originally buried may have changed and they may be exposed.

(L 649-2015) 21/15