



Page 228—Paragraph 357, lines 2 to 3; read:  
has a dredged channel from **Mosquito Cove** to the head. In  
1994, the controlling depth was 2½ feet in the right half of  
the channel with shoaling to less than a foot in the left half ...  
(BPs 153032-33; CL 1282/94) 51/00

Page 243—Paragraph 139, lines 1 to 2; read:  
In March 1999, the midchannel controlling depth was 8  
feet in the channel from Point Lookout ...  
(BPs 168573-74; CL 970/99) 51/00

Page 259—Paragraph 205, lines 4 to 6; read:  
faces southeastward. In January 1998, the channel leading to  
the pier on the west side of the island had a controlling depth  
of 13 feet, with depths of 11 feet along the northwestern and  
eastern edges of the dredged area near the pier.  
(CL 2064/99; BPs 169993-94; 51/99 CG1) 51/00